

Obion County Fair

Demolition Derby Rules

- 1.) All glass chrome mldges, etc. removed
- 2.) Battery and gas tank relocated inside car
- 3.) DOT Tires ONLY
- 4.) No weld or added metal to body or frame (except drivers door & bumper shocks)
- 5.) No frame seams welded
- 6.) Body mounts remain intact. Bolts or threaded rod no more than 5/8 inch thru body mounts 4 places thru deck lid & hood chained or bolted. If car has plastic inner fenders you may weld a plate no wider than 4 inches on hood & fender with one bolt on each side no larger than 5/8 bolt.
- 7.) Bumpers can be chained. If chained to hood that will be considered two of 4 places fastened.
- 8.) Cage can be welded inside car no further than 8 inches past front door. (6 inches if 2 door or 10 inches off the floor)
- 9.) No suspension changes or welding. Driver may use 2 spring risers on each front spring. Rear springs can be wired or small chained.
- 10.) Each end of spring, no chaining humps.
- 11.) No chains running from body to frame
- 12.) Transmission coolers & fans allowed
- 13.) If bumpers are changed, NO added metal. Clean welded to shocks
- 14.) No Imperial or after market bumpers.
- 15.) No extra body bolts allowed
- 16.) No pre-bending body or frame (driver may cut frame for bending, but do NOT weld the split.)
- 17.) No distributor protectors or gas tank protectors.